



acontis technologies GmbH

SOFTWARE

EC-Simulator

Release Notes

Version 3.2

Edition: November 2, 2023

EtherCAT® is registered trademark and patented technology, licensed by Beckhoff Automation GmbH, Germany.

© Copyright **acontis technologies GmbH**

Neither this document nor excerpts therefrom may be reproduced, transmitted, or conveyed to third parties by any means whatever without the express permission of the publisher. At the time of publication, the functions described in this document and those implemented in the corresponding hardware and/or software were carefully verified; nonetheless, for technical reasons, it cannot be guaranteed that no discrepancies exist. This document will be regularly examined so that corrections can be made in subsequent editions. Note: Although a product may include undocumented features, such features are not considered to be part of the product, and their functionality is therefore not subject to any form of support or guarantee.

Contents

1	New Features	4
2	Migration	5
3	Enhancements/bug fixes	6

1 New Features

2 Migration

2.1 From V3.1

- Replace emIII8254x by emIIIIntelGbe and support of TTS for Intel ® i210 and i211
- Rename RAS client and server to EcSimulatorRasClient, EcSimulatorRasServer
- Rename emPerfMeasInternal to emPerfMeas, old deprecated API removed

3 Enhancements/bug fixes

3.1 V3.2.1.02

Enhancement

- Add HiL/SiL-specific Quick Start Guide
- Add Sync Manager polling if AL Event disabled in Sync Manager Control Register
- Skip physical slaves at license check slave count
- Add esGetSlaveInpVarByObjectEx(), esGetSlaveOutpVarByObjectEx()

Fixes

- Fix EcMasterDemoMotion command line parsing if started with DemoConfig.xml (regression since V3.2.1.01)
- Fix timing task CPU affinity
- Fix potential naming conflict of Expat library
- Fix crash in EcSimulatorSilDemo on shutdown with pcap recorder enabled
- Fix support for MAC independent license key (regression since V3.1.4.09)
- Fix process data partially not updated due to wrong FMMU copy length
- Fix EC_T_MBXTFER::eTferStatus update in esCoeGetEntryDesc(), esCoeSdoDownloadReq(), esCoeSdoUploadReq(), esCoeGetODList(), esCoeGetObjectDesc()
- Fix missing context for esSetSlaveCoeObjectTransferCallbacks()
- Fix console logging freeze on RTOS-32 (regression since V3.1.4.05)
- Enable DC unit for ESCs with 3 or more ports
- Fix slave data lookup error if configured station address at simulator differs from master
- Fix cycle time performance measurement is implemented in eUsrJob_SendAllCycFrames instead of eUsrJob_StartTask (regression since V3.1.2.03)
- Fix registered client lookup on notification
- Fix esGetSlaveId(), esGetSlaveFixedAddr() for SIMULATOR_SLAVE_ID
- Fix missing string termination in SDO value log message of DEFTYPE_VISIBLESTRING in CoeReadObjectDictionary() in examples
- Fix Master OD reading canceled at RX PDO mapping and TX PDO mapping in CoeReadObjectDictionary() in examples

Platform

- Remove support for T-Kernel and eT-Kernel
- Add FP Real-time Accelerator for Windows
- Add support for Broadcom BCM5719 (emllBcmNetXtreme)
- Remove obsolete EC_LINKIOCTL_REGISTER_FRAME_CLBK, EC_LINKIOCTL_UNREGISTER_FRAME_CLBK
- Add MAC Protection for Rockchip RK3588 and RK3568
- Use poll() or epoll() instead of select() for sockets
- Add support for i.MX93 to emllFslFec
- Fix support for KSZ9131 (disable EEE in Phylib)

- Add EC_T_LINK_PARMS_GEM::bNotUseCacheSync to fix performance issue with emllGEM e.g. on older systems by disabling internal LinkOsCacheDataSync() (default: enabled)
- Add support for MAC protection to emllDW3504 on Rockchip RK3399
- Fix crash in rt_task_inquire due to bug in Xenomai3 API
- Fix emllIntelGbe EcLinkGetSpeed()
- Fix DW3504 Altera Cyclone Performance issue by turn off cache sync
- Fix memory leak in emllAlteraTSE
- Fix emRasSrvStop hangs on EC-Win(RTOS-32)
- Configure TTS interrupt only if EC_T_LINK_PARMS_ICSS::TtsParms::pfnStartCycle set
- Fix emllRZT1 MAC address reset
- Fix RAS server on RTX64 (broken since V3.1.4.01)
- Fix threading on TI-RTOS AM65x (e.g. RAS server starved)

3.2 V3.2.1.01

- Extend EC_T_SIM_SLAVE_CFG_INFO, EC_T_SIM_SLAVE_STATUS_INFO
- Add EC_T_SIMULATOR_INIT_PARMS::bApiLockByApp
- Add pdwVersionType parameter to esGetVersion() EC-Simulator
- Add CopyInfo to EC_T_PROCESS_VAR_INFO
- Change IPv4 parameter variables type from EC_T_DWORD to EC_T_IPADDR
- Remove legacy performance measurement APIs
- Rename RAS client and server to EcSimulatorRasClient, EcSimulatorRasServer
- Rename esPerfMeasInternalXxx to esPerfMeasXxx
- Fix crash in esConfigureNetwork() if network already configured
- Fix occasional AoE mailbox data corruption
- Fix missing SM_CHANGE_EVENT when byte containing Sync Manager Enable Bit (0x0806, 0x080E, 0x0816,...) is written
- Fix reentrancy of esInitSimulator() after esInitSimulator() was called with bad parameters

Platform

- Add pdwSpeed parameter to EcLinkGetSpeed
- Add support for 64Bit DMA physical address on INtime6
- Add szLoadPath to EC_T_LINK_PARMS
- Add QNX SMMUMAN support
- Add support for Rockchip DW3504
- Add support for IRQ CPU affinity on Linux
- Add device IDs for Intel Pro/1000 (i8254x) I226
- Add support for Xilinx KR260 SGMII Port
- Fix INVALID_STATE in CEcWrapperDotNet::DeinitInstance() if started with MbxGatewaySrv
- Add support for SGMII on Marvell 88E1510 for Intel DW3504
- Fix DW3504 Rockchip Clocks and second Instance

- Fix EcatDrv to support KeTimer period < 16ms
- Fix emIIntelGbe EcLinkGetSpeed()

3.3 V3.2.0.03

- Use default TaskId 0 if eUsrJob_StartTask called with EC_NULL
- EC_COPYBITS_INLINE declare EC_T_BYTE* pbySrc as const
- Add esGetCfgSlaveEoeInfo()
- Add support for CoE object entry gaps
- Fix IntelGbe EclinkOpen() faulty log messages
- Fix RAS protocol corruption in case of concurrent send requests at server
- Fix force process data after FMMU start
- Fix CoE upload error also ignored if ignore CoE download set
- Fix crash in EC-Wrapper .NET if variable size exceeds 512 bytes
- Fix text translation crash in EC-Wrapper

Platform

- Add support for ecatGetCfgSlaveInfo() to RAS client on PPC
- Add Device ID for Intel Pro/1000 I82545EM Copper
- Fix occasional lock-up at stopping acceptor thread in emRasSrvStop(...)
- Update atemsys V1.4.25
- Add IOCTL_INT_CPU_AFFINITY EC-Simulator
- Add Device Tree Ethernet driver support for RockChip

3.4 V3.2.0.02

- Add SSC_APPL-callback EC_T_SLAVE_SSC_APPL_DESC::pfnMainInit for APPL_MainInit
- Add simulator id and slave address to EC_PF_SSC_APPL-callbacks
- Set calling convention at EC_PF_SSC_APPL-callbacks
- Add esEoeSendFrame() and support for pfnEoeReceive and pfnEoeSettingInd
- Add support for APRW and FPRW
- Add esEoeSendFrame() and support for pfnEoeReceive and pfnEoeSettingInd
- Add esSetSlaveAoeObjectTransferCallbacks()
- Add esGetSimSlaveInfo()
- Add “-maxbusslaves” parameter to examples
- Fix support for MAC independent license key
- Fix value distribution for min and max bin in performance measurement histogram
- Fix support for ULINT datatype from EXI (e.g. Timestamp Object 0x10F8)
- Fix esGetMasterState() at startup
- Remove systematical delay of 250ms within emConfigLoad(), emConfigureMaster(), emConfigExtend(), emDeinitMaster(), emRescueScan(), emSelfTestScan()

- Fix duplicated frames logging

Platform

- Microsoft ® Windows ® Visual Studio ® project files updated to VS2015
- Add EC_T_LINK_PARMS::dwLinkSpeed
- Add wait within EcLinkRecvFrame() for all previously sent frames returned to emllProxy
- Add esVoeSend() over RAS
- Fix API call over RAS delayed if a parallel RAS connection is broken
- Add support for STM32MP135 to DW3504
- Add PartialImage libraries for VxWorks70 linklayers
- Add support for ecatNotifyApp() from RAS Server application to RAS Client application
- Change connection type from UDP to TCP for emllProxy
- Fix memory leak in RAS Client if connection lost while EoE-Endpoint active
- Fix EC_COPYBITS out-of-bounds read from pbySrc
- Fix all printf replaced with EcLogMsg in LinkOsLayer for VxWorks
- Update atemsys V1.4.24
- Fix PCI bars
- Add Device Tree Ethernet driver support for STM32mp135

3.5 V3.2.0.01

- Update to expat V2.4.9
- Add IstStackSize to all Linklayers parameters
- Change Mutex default setting for Linux
- Add support for VxWorks MSI
- Add PartialImage libraries for VxWorks70
- Obsolete .NET and Python interface classes, enums and methods removed
- Update atemsys V1.4.22
 - Fix Build Warnings
 - Fix kernel config depending irq structures
 - Fix kernel version 4.12 to 4.15 for handle of dma_coherent bit
 - Add IOMMU support, new mapping to userspace active and tested for kernel > 5.4, use old mapping with ATEMSYS_LEGACY_DMA=1 define or activate new mapping with ATEMSYS_LEGACY_DMA=0 define for older kerne

3.6 V3.1.4.08

- Add EC-Simulator Linux HiL x86 32 Bit Dongled
- Add esSendSlaveCoeEmergency()
- Fix JobTask cycle time in Python examples
- Fix performance measurement in EcSimulatorHilDemoPython
- Fix assert on cyclic frame processing for slaves with sync units containing empty PDOs only
- Fix EC_T_CFG_SLAVE_INFO::wNumProcessVarsInp, EC_T_CFG_SLAVE_INFO::wNumProcessVarsOutp from esGetCfgSlaveInfo() due to erroneously skipped entries by variables not assigned to any slave

Platform

- Add support for VxWorks MSI
- Fix lock-up in emllProxy EcLinkClose() on Windows

3.7 V3.1.4.07

- Call myAppWorkpd() after cyclic frame processing in EcSimulatorHilDemoMotion in Interrupt Mode
- Fix performance measurement in EcSimulatorHilDemoMotion

Platform

- Add EcSimulatorHilDemoMotion for INtime6, QNX7, QNX71, VxWorks70
- Fix VxWorks RTP AtemSys pipe release
- Fix memory violation leading to undefined behavior like crash or erroneous timeout during DC related InitCmd on VxWorks70 PPC and x86 with emllSnarf, SystemTime() since VxWorks70SR660 and DMA on x86 since VxWorks70vw2203

3.8 V3.1.4.06

- Add error simulation between real slaves
- Add support for 12 slaves license limit
- Fix slave information prints contain "ERROR: Not found" in examples
- Increase log buffer in examples
- Fix EcSimulatorHilDemoMotion parameter handling
- Fix CoE emergency if SOE_SUPPORTED in SSC (SOE_EMERGENCY_SUPPORTED=0)
- Remove BlockNode handling from CEmNotification
- Fix crash in case of invalid ENI containing a hot connect group head slave with physical address equal to zero

Platform

- Add link status state machine to emllBcmGenet
- Add support for Linux ARM 32 Bit to emllBcmGenet
- Force disconnection using PHY loopback for emllI8254x if ResetOnDisconnect not set
- Add support for emllTiEnetIcssg on AM64xEVM with FreeRTOS
- Add emllDW3504 for Xenomai

- Select 'ECAT Protocol Driver' installation on Windows by default if not currently installed
- Fix PCI link layer support for QNX ARM 32 Bit
- Add DCM MasterShift for QNX
- Fix missing ATEMRAS_NOTIFY_CONNECTION EMRAS_EVT_SERVERSTOPPED on connection termination by server
- Fix TX hang in emlll8254x for I219 after uncontrolled termination
- Fix lock-up in EC-Wrapper RAS connection on termination by server
- Set default stack size to 0x8000 for 64 Bit architectures

3.9 V3.1.4.05

- Add frame RX time to DC simulation
- Add EC_LINKIOCTL_GET_ONTIMER_CYCLETIME, EC_LINKIOCTL_SET_ONTIMER_CYCLETIME, EC_LINKIOCTL_ONTIMER to SiL
- Fix compiler errors for EXCLUDE_EC_SIMULATOR_HIL, EXCLUDE_EC_SIMULATOR_SIL, EXCLUDE_INTERFACE_LOCK, EXCLUDE_MASTER_OBD and INCLUDE_PERF_MEAS
- Set EC-Master cycle time as EC-Simulator SiL cycle time by default in emInitMaster()
- Fix missing loop closed info in DL status for initially disconnected ports
- Fix no messages in error log if NOPRINTF defined
- Set cycle time parameter in EcSimulatorHilDemo

Platform

- Add Xenomai3 ARM 64Bit support to RTL8169
- Add support for Universal WIBU Code
- Add emllBcmGenet for Raspberry PI 4 (BCM2711)
- Fix reset MAC address at DW3504
- Fix memory leak in OsCreateEvent() on Linux, Xenomai, RTEMS and SylixOs in case of semaphore initialization error

3.10 V3.1.4.04

- Add pOsParms to EC_T_LINK_PARMS_SIMULATOR
- Fix EcSimulatorHilDemo startup error
- Fix EcSimulatorSilDemo startup error

Platform

- Add support for Xenomai3 ARM 64Bit
- Add support for VxWorks70

3.11 V3.1.4.03

- Fix access to some object types by implicitly pad entries to even 16bit memory addresses (SSC OBJ_WORD_ALIGN)
- Add “-oem” command line parameter to examples
- Add AtesRasClient
- Add notification logging (e.g. slave state change) to EcSimulatorHiLDemo
- Fix memory leak in SSC on AoE read and SDO info
- Fix memory leak in esInitSimulator if called with invalid parameters
- Fix EC_IOCTL_ISLINK_CONNECTED on start

Platform

- Increase resolution for OsSystemTimeGet() on Windows
- Add bDisablePromiscuousMode and bDisableForceBroadcast parameters to emllNdis
- Add absolute path support alternative to OsGetLinkLayerRegFunc for VxWork70
- Fix counter overrun in OsQueryMsecCount on VxWorks69 PENTIUM4
- Fix RTOS-32 is not supporting cycle times below 1000us (broken since V3.1.1.06)
- Fix occasional crash in RAS Server on EC_IOCTL_UNREGISTERCLIENT
- Fix occasional crash on emRasClntRemoveConnection after emRasSrvStop
- Fix Interrupt Mode support for emllProxy
- Fix Multi Tasks Configuration doesn't work with emllNdis Linklayer
- Fix memory leak on RAS socket disconnect while API call pending
- Fix to block emRasClntRemoveConnection, emRasSrvStop until all worker threads terminated

3.12 V3.1.4.02

- Add performance measurement level to -perf command line parameter
- Add emGetMemoryUsage over RAS
- Add link layer parameters help to Python example application
- Fix crash on simulator restart in OPERATIONAL
- Fix crash with DS402 and EXI containing Object Dictionary
- Fix occasional crash on concurrent call of esPowerSlave and EC-Simulator frame processing
- Fix occasional crash in emllSimulator IST
- Fix invalid write to second byte in buffer on esCoeSdoUpload with datalen = 1
- Fix invalid temp data read at end of CoE object type BYTE Array [0..n]
- Fix blocking API handling over RAS
- Fix command line contains unexpected application name in RTOS-32 config files

Platform

- Add Xenomai support
- Add MAC protection to emllFslFec for i.MX8 and i.MX8m
- Add “EcatDrv for Optimized Link Layers” to EC-Simulator HiL User Manual

- Fix CPSW transmit channels to work with acontis CPSW Linux driver patch

3.13 V3.1.4.01

- Add esVoeSend, esSetVoeReceiveCallback
- Add write support to read-only CoE objects
- Fix access to CoE SubIndex on odd word address
- HiL: Fix start with link disconnected and link reconnection
- Fix mailbox queue entries memory leak (SSC related)
- SiL: Increase IST stack size from 0x4000 to 0x8000
- SiL: Fix occasional lock-up in IST
- Don't call OsMeasCalibrate() if performance measurement is disabled
- Rename PerfMeas distances to offsets
- Fix AoE support for PPC

Platform

- Fix i8254x interrupt mode on ARM/AARCH64
- Fix AoE support for PPC
- Updated to ECAT NDIS Protocol Driver Setup V3.1.3.4. Hide command window during driver installation
- Updated to atemsys V1.4.20
 - Fix support for CMA (Contiguous Memory Allocator) for kernel > 4.9.00

3.14 V3.1.3.03

- Fix topology info if master assigns other addresses than in ENI/EXI
- No error on ScanBus request
- Add EC_T_MASTER_INFO::dwMasterStateSummary
- EC_T_MASTER_INFO::BusDiagnosisInfo data available even if compiled with EXCLUDE_MASTER_OBD
- Cycle time and JOB_Total timer missing in EcMonitor since V3.1.2.10

Platform

- Updated to atemsys V1.4.18
 - Remove obsolete ARM cycle count register(CCNT)
 - Fix PCI driver do registration for all Ethernet network adapters
 - Add modul parameter AllowedPciDevices to adjust PCI driver
- Add CPU affinity support to Link Layers supporting interrupt mode

3.15 V3.1.3.02

- Support ENI file with CU2508 only
- Alias can be used for all configured address command types (FPRD, FPWR, ...)
- Use station address as alias address in simulated default EEPROM (if EEPROM for the slave not explicitly set in EXI)
- Return simulated frame to master before post processing

Platform

- Add RTL8168H support to emllRTL8169
- Fix DMA buffer alignment in emllRTL8169 (regression since V3.1.3.01)
- Fix DMA allocation, requesting memory below 4GB for AARCH64/ARM64 on QNX
- Updated to ECAT NDIS Protocol Driver V3.1.3.2
 - Move promiscuous mode setting from NDIS Link-Layer to NDIS protocol driver
 - Add an entry “DontSetPromiscuousMode” in the Windows registry to avoid setting promiscuous mode in ECAT NDIS Protocol Driver
 - Rename Setup to “ECAT NDIS Protocol Driver”
- Fix EcatDrvGetDrvVersion on Windows (regression since V3.1.3.01)
- Fix DMA memory allocation address handling if base is > 2GB leading to permanent frameloss in VxWorks-32Bit
- Add RTL8125 support to emllRTL8169
- Add Link Layer IST CPU affinity mask and priority for .NET and Python
- Add CYCFRAME_RX_CB for .NET and Python
- Updated to atemsys V1.4.17.
Fix atemsys dma_set_mask_and_coherent() missing in kernels under 3.12.55
- NDIS fix start-up with link disconnected

3.16 V3.1.3.01

- Fix EC-Simulator HiL multi link Interrupt Mode
- Fix line crossed in mixed mode
- Implicitely IgnoreCoeDownloadError for EXI
- Add interrupt mode support for emllSockRaw
- Updated to EcatDrv V3.1.3.01 Add Print EcatDrv Version to Ecat Driver for Windows
- Fix parse PCI bus hardware ID string on Windows

3.17 V3.1.2.11

- Fix lock-up in esConfigureNetwork in case of link disconnected and only one slave configured
- Fix ERROR SDO: Toggle bit not alternated for ENI with segmented CoE InitCmds

3.18 V3.1.2.10

- Fix force process data (MixedMode)

3.19 V3.1.2.09

- Fix occasional lock-up in e.g. esSetSlaveSscApplication due to endless “wait until SyncManager is disabled”
- Fix auto increment address usage in case on line break
- Fix Bus Diagnosis Object 0x2002, SubIndex 4: Number of DC Slaves found
- Remove absent slave’s objects from 0x3nnn, 0x9nnn
- Fix esGetBusSlaveInfo wPrevPort not set
- Refresh OD on DL Status Change
- Fix return code of esGetBusSlaveInfo for absent slaves
- Fix Simulator OD on reconnect slave at other position
- Improve pcap recorder timestamps using OsPerfMeas
- Updated to atemsys V1.4.15
- Fix missing signal handler for SIGINT, SIGTERM on QNX
- Fix EcatDrv to support AuxClk period < 16ms
- Add 64Bit DMA support for RTL8169

3.20 V3.1.2.08

- Fix default port 0 connection of slaves with wHCIdentifyAddrPrev (busmismatch)
- Add SlaveID to BusSlaveInfo
- Fix EK1200 support
- Add EC_NOTIFY_HC_TOPOCHGDONE for esPowerSlave, esDisconnectPort, esConnectPorts
- Increase MAX_MBX_WRITE_ADDRESS

3.21 V3.1.2.07

- Fix identity object (0x1018) in case of Default Object Dictionary for PPC

3.22 V3.1.2.06

- Add eCnfType_Data for SiL
- Add FSoE
- Add EoE supported detection support
- Add EC_IOCTL_SIMULATOR_SET_MBX_PROCESS_CTL, EC_IOCTL_SIMULATOR_GET_MBX_PROCESS_CTL
- Fix HiL with winpcap
- Fix WKC for multi sync unit slaves on LRW
- Fix performance measurement

3.23 V3.1.2.05

- Fix esForceProcessDataBits for multiple slaves' INPUTs

3.24 V3.1.2.04

- Add Mixed Mode 2: Real slave between simulated slaves
- Fix Process Data Image Sync for Process Data below Ado 0x1000
- Fix esSetProcessDataBits for INPUTs, e.g. EcSimulatorHiLDemoPython
- Fix missing EcWrapper for HiL
- Fix encrypted ENI/EXI accepted if OEM key missing (esSetOemKey)
- Fix missing interrupt callback registration at link layer for HiL
- Fix last SimSlave CoE object missing at esCoeGetODList
- Fix occasional crash in esResetSlaveCoeObjectDictionary

3.25 V3.1.1.07

- Add Object 0x2001 "Master State Summary", Bit 8: Slaves in requested State

3.26 V3.1.1.06

- Discard process data variables not assigned to slaves e.g. variables from “Image-Info” in TwinCAT are out of allocated “Image”
- Replace MAC address fall back AA:BB:CC:CA:FE:xx with 00:00:00:00:00:xx
- Fix occasional crash in EXI loading

3.27 V3.1.1.05

- Fix EC-Simulator SiL Dongled delivery

3.28 V3.1.1.04

- Fix NULL pointer crash in EcSimulatorHilDemo::RasNotifyCallback
- Add SONAME for libEcSimulator.so on Linux
- Add interrupt mode for EC-Simulator HiL
- Add Mixed Mode with EC-Simulator at end support (Mixed Mode 1)
- Add /EtherCATConfig/Config/ExtendedInfo/Entry/Slaves/Slave/Simulated support
- Fix process image sync with copy offset (TwinCAT ENI)
- Skip “not used sync managers shall be disabled” check (non-acontis Master)
- Fix DPRAM from process image sync (forced data)
- Prevent lock-up in esConfigureNetwork if circulating topology provided

3.29 V3.1.1.03

- EC-Master supports EC-Simulator SiL license
- Add slave address in CoE object transfer callbacks
- Fix station address look-up order in esGetSlaveId

3.30 V3.1.1.02

- Add supported Mbx Protocols to esGetCfgSlaveInfo, esGetSlaveInfo
- CiA402 axis simulation enabled only for ApplicationName “DS402” in EXI (Regression since V3.1.1.01)
- Add “-simulator ... -connect” option for e.g. Cable Redundancy
- esLogFrameEnableAtSlavePort, esLogFrameDisableAtSlavePort
- Add esSetLinkDownAtSlavePort, esSetLinkDownGenerationAtSlavePort, esResetLinkDownGenerationAtSlavePorts
- Add esSetErrorAtSlavePort, esSetErrorGenerationAtSlavePort, esResetErrorGenerationAtSlavePorts
- Fix emInitSimulator invalid parameters logging
- Add EXI parsing “PowerOff”, “PortConnection”, “IgnoreCoeDownloadError”

- Add EC_NOTIFY_SLAVE_PRESENCE
- Fix esIsSlavePresent

3.31 V3.1.1.01

- Fix Object dictionary reset for esSetSlaveSscApplication
- Add pvContext to esSetSlaveCoeObjectTransferCallbacks
- Fix FoE, SDO transfers in SSC for PPC
- Fix esGetSlaveInpVarInfoEx, esGetSlaveOutpVarInfoEx

3.32 V3.1.0.20

- Add EL6695 support (extend slave RAM size to 0xA000)
- Fix invalid CoE access due to mismatched TYPEDEF_ARRAY_... bit offset
- Fix invalid process data access in simulated slave application

3.33 V3.1.0.19

- Add RAS support to EcMasterDemoMotion with EC-Simulator SiL
- Add EC_IOCTL_REGISTER_CYCFRAME_RX_CB
- Simulator API calls over RAS esPowerSlave, esDisconnectSlave, esConnectSlaves
- Fix unknown tag warnings on startup with EXI
- Fix memory leak in Diagnosis History object of SSC
- Check Sync Manager settings according to ENI/EXI
- Fix INPUTs access from application
- Fix WKC error for Slaves with zero-lengthed FMMUs / Sync Managers
- Add Multi Sync Manager Channel support to SSC and EC-Simulator
- Fix EC-Simulator SiL OnTimer Thread on INtime
- Fix DS402 after esPowerSlave
- Clear slave inputs on slave power off

3.34 V3.1.0.18

- Fix crash on esPowerSlave with object dictionary from EXI or application
- Fix link layer based license key handling (HiL)
- Fix Reference Clock position for auto-connect floating hot connect
- Ignore empty RECORD / ARRAY data types
- Ignore SoE writes exceeding object's default buffer size
- Fix WIBU Product Code for EC-Simulator Dongled
- Fix partially uninitialized Object Entry Data (EXI)

- Fix occasional crash due to 0x3002 “Outputs” SDO structur (generic OD)
- Fix object length on SDO complete access download according to object description
- Fix missing awaiting all APIs have finished in esDeinitSimulator
- Fix illegal unlock in ReleaseInterface if EC-Simulator compiled with EXCLUDE_INTERFACE_LOCK
- PDI read OUTPUT Sync Manager already in SAFEOP to prevent WKC errors (simulated slaves with Process Data in Mailbox Mode)
- Ignore 0x1C33, SubIndex 1: Synchronisation type. Needed for simulated slaves with Process Data in Mailbox Mode.
- Add esSetLicenseKey to EcSimulatorHilDemo
- Extended 0x1C12 / 0x1C13 to 16 entries (PDO_ASSIGN_CNT)

3.35 V3.1.0.17

- Add INPUTs from Process Data Image for slaves without device emulation
- Add initially connect / disconnect all hot connect groups
- Add handler for unknown data type in Object Dictionary
- Add esResetSlaveCoeObjectDictionary
- Add esGetNumConnectedSlaves, esGetNumConnectedSlavesMain,
- Add esIsSlavePresent (linked in topology and powered on)
- Add slave information to identity object (0x1018) for default Object Dictionary
- Fix CoE OD memory leak in esSetSlaveSscApplication
- Fix slave SSC default application flash support
- Fix ecatPerfMeas
- Fix crash in esSetSlaveSscApplication for default handlers
- Fix memory leak in Object Dictionary in case of esSetSlaveSscApplication
- Fix memory corruption during logical command parsing
- Change esGetSlaveIdAtPosition: Use auto increment address from ENI/EXI
- Change licensed slave count (24 / 64 / 128 / 256)
- Add EC-Simulator-SiL-Linux-x86_32Bit-Dongled
- Refactor emllSimulator as wrapper for EcSimulator. SiL delivery contains EC-Simulator core library.
- Rename esRemoveSlaveCoeObject to esDeleteSlaveCoeObject
- Rename esAddSlaveCoeObjects to esExtendSlaveCoeObjectDictionary

3.36 V3.1.0.16

- Add esSetLicenseKey for HiL (incl. MAC based key) and SiL
- Refactor emllSimulator as wrapper for EcSimulator (SiL)
- SiL: bDisableProcessDataImage, bJobsExecutedByApp defaults to FALSE
- Add EcSimulatorSilDemo
- Apply forced INPUTs to Process Data Image
- Add esGetSlaveIdAtPosition using auto increment address from ENI/EXI
- Add wNumProcessVarsInp, wNumProcessVarsOutp to esGetCfgSlaveInfo
- Add esClearSlaveCoeObjectDictionary, esRemoveSlaveCoeObject
- Add esCoeSdoDownload, esCoeSdoUpload
- Add esCoeGetODList, esCoeGetObjectDesc, esCoeGetEntryDesc for slaves
- Add esSetSlaveSscApplication
- Add esAddSlaveCoeObjects
- Add esSetSlaveCoeObjectTransferCallbacks
- Apply mailbox settings from ENI/EXI to EEPROM default content
- Increased SSC mailbox limits
- Add RAS server to emllSimulator (SiL)
- Add DL control feature “Temporary use of settings in 0x0100:0x0103[8:15]”
- Parse Hot Connect identification (Ado134, EEPROM, DPRAM) from ENI/EXI
- Add object mappable as TxPDO / RxPDO parsing from EXI
- Add object access restrictions parsing from object dictionary in EXI
- Updates to EXI parsing for new EXI format, e.g. Slave Application
- CiA402 axis simulation enabled only for ApplicationName “DS402” in EXI
- Add OEM EXI support
- Add initial memset for slave process data
- Add EC-Simulator OD reading support to EC-SlaveTestApplication
- Fix EC-Simulator OD reading (regression since V3.1.0.15)
- Re-init slave on power cycle (esPowerSlave)
- Deny BOOTSTRAP and mailbox protocols requests not enabled at ENI slave
- Fix esSetSlaveState to higher state denied
- Fix crash in esSetSlaveState for Device Emulation (not supported)
- Fix occasional crash in SSC CoE read
- Fix occasional crash in SSC Mailbox handler
- Fix crash if DS402 activated without Target Velocity
- Ignore complete access to simple object PDO config (legacy ESI support)
- Return coherent port receive times even if input port is not port A, supporting junction redundancy and line crossed topologies

3.37 V3.1.0.15

- Fix cyclic mailbox state cmd for HiL
- Fix ECAT Event Mask (0x0200) register refresh
- Prevent endless loop in ReceiveFrame
- Set port mode auto (revert auto-close) on slave power on
- Fix AoE for Linux x64
- Fix EC-Simulator HiL with SockRaw
- Add NDIS link layer
- Fix VendorId, ProductCode, RevisionNumber, and SerialNumber internally get from EEPROM as WORD instead of DWORD, leading to missing tabs in EC-Engineer

3.38 V3.1.0.14

- Add esSetSlaveState
- Add esReadSlaveIdentification
- Add esGetSlaveStatistics / esClearSlaveStatistics
- Fix esGetBusSlaveInfo returning erroneous children slaves information
- Add CiA402 simulation
- Add esSetOemKey for AtesRasSrv
- Add EC-Engineer MDP scan support using online EXI
- Add CoE Object Dictionary from EXI
- Extend default RxPDOs, TxPDOs 0x1600...0x1603, 0x1A00...0x1A03, SI 1...8 (writeable)
- Ignore CoE download error in case of default Object Dictionary
- Add INPUT setting by EC-Engineer support
- Fix EC-Simulator device information in Object Dictionary
- Add abyMac, dwRxBufferCnt, dwBusCycleTimeUsec, bJobsExecutedByApp, qwOemKey to EC_T_LINK_PARAMS_SIMULATOR
- Add missing SDK\INC\EcSimulator.h to EC-Simulator SiL
- Fix EC-Simulator SiL Process Data Image support
- Fix esGetNumConfiguredSlaves

3.39 V3.1.0.13

- Add esConnectPorts, esDisconnectPort, esPowerSlave to EcSimulator.def
- Update SSC from V5.11 to V5.12
- Add EC-Simulator-HiL-QNX6
- Fix CPU Affinity for emllSimulator

3.40 V3.1.0.12

- Refresh AL Status and Control in object dictionary
- Add esGetSlaveId, esGetSlaveFixedAddr, esGetSlaveProp, esGetSlaveState, esGetSlaveInfo
- Add EC-Simulator-HiL-QNX7
- Add frame logging
- Add Network Operation Functions (esConnectPorts, esDisconnectPort, esPowerSlave)
- Fix occasional crash in ProcessFrame
- Add EEPROM write by EtherCAT support

3.41 V3.1.0.11

- Add EC_NOTIFY_SLAVE_STATECHANGED
- Add RegisterClient / UnregisterClient
- Add EK1200 support
- Device Emulation for non-mailbox slaves if Extended Info not available for slave
- Increase MAX_PD_WRITE_ADDRESS, MAX_PD_READ_ADDRESS to end of DPRAM (0x3FFF)
- Device Emulation for non-mailbox slaves if Extended Info not available for slave
- Support Port Receive Times
- Add EcSimulatorHiLDemo

Platform

- Add Linux
- Add Windows